

M2S090S EVAL KIT EEPROM Programming Procedure

- 1. Install drivers from the CDM v2.10.00 WHQL Certified Rev1 folder.
- 2. Install FT_PROG from the FT_Prog_v2.8.2.0 folder. For additional help: http://www.ftdichip.com/Support/Utilities.htm (Search for FT_PROG).
- 3. Connect USB cable (mini USB to Type A USB cable) to J33 and other end connect it to USB port of test PC.
- 4. Run FT_PROG. Window will open as shown below.




5. Hit **F5** key to run "**Scan and Parse**" command. Below window will appear:



- 6. Right click on "Device: 0" on the left window.
- 7. Select "Apply Template" then "From File".
- 8. Select "UART.xml". This file will be provided in the Programming Procedures folder.

9. After selecting "UART.xml" below window will open.



10. Select "Program Device".