Subbasin	Non-PVC	PVC	Total	Treated- 2015	Treated- 2016	Treated- 2017	Treated- 2018	Treated- 2019	Treated- 2020-2021	Total Treated
CC05	43477.1	18422.52	61899.67		20218.15					20218.15
PVC treated: Non PVC Treated:					2584.52					
Non PVC Treated:					17633.63					
CC21	102283.1	37468.30	139751.45		71476.51					71476.51
PVC treated: Non PVC Treated:					7350.74 64125.77					
GC16	67774.0	8378.83	76152.84			374.96			65135.13	
PVC treated:				894.25		374.96			31233.59	
Non PVC Treated:				377.64		0			33901.54	
MC02	116472.4	16808.17	133280.64						107526.	
PVC treated: Non PVC Treated:				25701.02 35078.85					8156.569 99369.53 <sup>2</sup>	
									33333133	
RB05 PVC treated:	81449.4	29836.83	111286.24							0.00
Non PVC Treated:										0.00
SB04	98488.3	2 23604.57	122092.89		7154.743628				27916.61392	
PVC treated: Non PVC Treated:					1551.88 5602.86				4627.6 <sup>4</sup> 23288.9	
Non PVC Treateu.					5002.00				25200.9	
SB05	50438.6	3263.36	53702.02		13079.42				17024.2752	
PVC treated: Non PVC Treated:					0.00 13079.42				229.3 16794.98	
		4000.0-	400=00.00				440=-4-	44		
SR01 PVC treated:	7956.32	100772.67	108728.99				14975.17 12796.72			60726.96
Non PVC Treated:							2178.45			
SR04	55496.90	50086.98	105583.88				60632.42	221.48		60853.90
<b>PVC</b> treated:							9638.45	111.04		
Non PVC Treated:							50993.97	110.44		

















