DESCRIPTION	**HO2S fuel injection control system:** • P2096:00: Air fuel too lean • P2097:00: Air fuel too rich

Item

STEP	INSPECTION	RESULTS	ACTION

STEP

STEP