DTC P2302:00 [SKYACTIV-G 1.3, SKYACTIV-G 1.5]

id0102q1743000

2,000 rpm or less, the signal input to the PCM from ion sensor No.1 is in error.

Diagnostic supMort note

DTC
P2302:00

STEP