
DTC P0171:00 [SKYACTIV-G 1.3, SKYACTIV-G 1.5]

id0102q1934200

Note

- To determine the malfunctioning part, proceed with the diagnostics from "Function Inspection Using M-MDS".



STEP

STEP

STEP

STEP