INAPPROPRIATE OPERATION AND CONTROL RECODE 0x51 (COLD CONDITION DAMAGE PREVENTION CONTROL) [SKYACTIV-D 1.5]

id0102q2043300

Outline

- If oil dilution occurs due to fuel infusion and the ambient temperature falls below freezing, the fuel in the engine oil will freeze. As a result, the fuel injection amount is controlled due to insufficient engine oil lubrication which leads engine burn.

Operation Conditions

- When all of the following conditions are met, the engine oil pressure does not increase even if the engine is started.
  - — Engine coolant temperature at engine start is -18 °C {-0.40 °F} or less
  - — Engine oil dilution due to fuel infusion occurs

Protection Control

- Controls engine speed to idle speed.

Diagnosis Procedure and Explanation to Customer

STEP	INSPECTION		ACTION
1	**PURPOSE: VERIFY DTCs** • Has any DTC been stored?	Yes	Repair the malfunctioning location according to the applicable DTC troubleshooting. (See DTC TABLE [SKYACTIV-D 1.5])
		No	Explain to the customer that the vehicle is normal and the control was performed to protect the engine.