DTC P2459:00 [SKYACTIV-D 1.5]

id0102q2135900

DTC P2459:00	Abnormal diesel particulate filter regeneration interval short distance
DETECTION CONDITION	• After driving the vehicle at a PM accumulation amount equivalent to **3 g/l {0.187 lb/ft^3} or more**, the distance the vehicle was driven from the previous diesel particulate filter regeneration to the next diesel particulate filter regeneration is any of the following. — **39—69 km {25—42 mile}** occurs **44 times or more** — **70—99 km {44—61 mile}** occurs **115 times or more** **Diagnostic support note** • This is an intermittent monitor (other). • The check engine light does not illuminate. • FREEZE FRAME DATA is not available. • Snapshot data is available. • DTC is stored in the PCM memory.
FAIL-SAFE FUNCTION	• Not applicable
POSSIBLE CAUSE	• Fuel injector malfunction • Fuel line clogged • Soot generation amount is high due to abnormal engine combustion • Exhaust gas pressure sensor No.2 malfunction • Difference in pressure between exhaust gas pressure before and after passing diesel particulate filter is high • Soot cannot be removed by compulsory diesel particulate filter regeneration • Supply pump malfunction • HP-EGR control valve malfunction • Intake shutter valve malfunction • Turbocharger with variable turbine geometry malfunction • PCM malfunction

Diagnostic Procedure

STEP	INSPECTION		ACTION
1	**RECORD VEHICLE STATUS WHEN DTC WAS DETECTED TO UTILIZE WITH REPEATABILITY VERIFICATION** **Note** • Recording can be facilitated using the screen capture function of the PC. • Record the freeze frame data/snap shot data.	—	Go to the next step.
2	**VERIFY RELATED SERVICE INFORMATION AVAILABILITY** • Verify related Service Information availability. • Is any related Service Information available?	Yes	Perform repair or diagnosis according to the available Service Information. • If the vehicle is not repaired, go to the next step.
		No	Go to the next step.
3	**VERIFY RELATED PENDING CODE AND/OR DTC** • Switch the ignition off, then ON (engine off). • Perform the Pending Trouble Code Access Procedure and DTC Reading Procedure. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) • Are any other PENDING CODEs and/or DTCs present?	Yes	**If DTC P243C is stored** • Repair the malfunctioning location according to the applicable DTC troubleshooting, then go to the next step. (See DTC P243C:00 [SKYACTIV-D 1.5].) **If DTC other than P243C is stored** • Repair the malfunctioning location according to the applicable DTC troubleshooting, then go to the next step. (See DTC TABLE [SKYACTIV-D 1.5].)
		No	Go to the next step.
4	**VERIFY VALUE OF PID DET_CNT_L1 (INTERVAL FOR NUMBER DIESEL PARTICULATE FILTER REGENERATIONS IS 39—69 KM {25—42 MILE}) USING M-MDS** • Access the DET_CNT_L1 PID using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) • Is the value indicated for DET_CNT_L1 **44 times or more**?	Yes	Go to the next step.
		No	Replace the fuel injector in all of the cylinders, then go to the next step. (See FUEL INJECTOR REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)

STEP	INSPECTION		ACTION
5	**VERIFY VALUE OF PID DET_CNT_L2 (INTERVAL FOR NUMBER DIESEL PARTICULATE FILTER REGENERATIONS IS 70—99 KM {44—61 MILE}) USING M-MDS** **Note** • If the value of PID DET_CNT_L1 is **44 times or less** under the vehicle detection condition of DTC P2459:00, the value of PID DET_CNT_L2 is **115 times or more**. • Access the DET_CNT_L2 PID using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) • Verify that the value of DET_CNT_L2 is **115 times or more**.	—	Go to the next step.
6	**PERFORM FUEL INJECTOR CARBON DEPOSIT BURN-OFF PROCEDURE** **Note** • Carbon on the exhaust valve is removed by performing the fuel injector carbon deposit burn-off procedure. • Perform the "FUEL INJECTOR CARBON DEPOSIT BURN-OFF PROCEDURE". (See FUEL INJECTOR CARBON DEPOSIT BURN-OFF PROCEDURE [SKYACTIV-D 1.5].)	—	Go to the next step.
7	**VERIFY DTC TROUBLESHOOTING COMPLETED** • Always reconnect all disconnected connectors. • Clear the DTC from the PCM memory using the M-MDS. (See CLEARING DTC [SKYACTIV-D 1.5].)	—	DTC troubleshooting completed.