STEP

STEP	INSPECTION	ACTION
2	Inspect the spark plugs for damage, wear, and proper plug gap. Is there any malfunction?	

STEP

STEP

- — Wiring harness between cooling fan relay No.1 and cooling fan motor (Fuse blown due to open circuit, short to ground)

8. Using the M-MDS simulation function, turn FAN1 from the of

- If not as specified, inspect the following:
  — OCV operation (See OIL CO

7. Remove the OCV while the connector is connected. (See OIL CONTROL VALVE (OCV) REMOVAL/ INSTALLATION [SKYACTIV-G 1.3, SKYACTIV-G 1.5].)
8. Switch the ignition ON (engine off).
9. Access the simulation item VT_EX_DES usin