NO.19 POOR FUEL ECONOMY [SKYACTIV-D 1.5]

id0103q2898600

19

- PCM DTC is stored.
- Fuel system malfunction (leak in supply system)
- A/C relay malfunction
- Fan control module malfunction
- ATX malfunction (ATX)
- Air cleaner malfu
- Mechanical b F a i n Pr cedure " .

2 **INSPECT FOR FUEL L**

STEP

STEP	INSPECTION	RESULTS


STEP