DRIVE SELECTION SWITCH REMOVAL/INSTALLATION [SKYACTIV- 1.3, SKYACTIV- 1.5]

id0121a2100200

1. Disconnect the negative battery cable. (S