BAROMETRIC PRESSURE (BARO) SENSOR INSPECTION [SKYACTIV-D 1.5]


id0140q2108700

PID/DATA Monitor Inspection

Note
- Because the BARO sensor is integrated in the PCM, replacing the BARO sensor includes replacement of the PCM.

1. Connect the M-MDS to the DLC-2.
2. Switch the ignition ON (engine off).
3. Verify that the PID BARO value (barometric pressure) is within the specification. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].)
   - If not as verified, replace the PCM. (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)

Specification (Reference)



am2zzw00011289