DTC C103(C1)6:41 [DSC HU/CM]

3 Select “TPMS Reset”.
• Using the M-MDS,go to the next st
(See DSC HU/CM REMOVAL/INSTA
(See DSC HU/CM REMOVAL/INSTA

