DTC P181F:00 [TCM (CW6A-EL)]

- Electric AT oil pump relay malfunction
- Short to ground in wiring harness between electric AT oil pump relay terminal A and electric AT oil pump relay