DTC P073D:00 [TCM (EW6A-EL)]

id0502p7905700

DTC P073D:00	**Neutral incorrect ratio**
DETECTION CONDITION	• In P or N position, the following phenomenon occurs: — Speed ratio is **0.5 or less** for **2 s** while vehicle is stopped in P or N position.
FAIL-SAFE FUNCTION	Not applicable
POSSIBLE CAUSE	• Clutch stuck • Turbine/input shaft speed sensor malfunction
SYSTEM WIRING DIAGRAM	Not applicable

Diagnostic procedure

STEP	INSPECTION		ACTION
1	**VERIFY DTC OUTPUT STATUS** • Are any the following DTCs displayed? — P0706:00, P0715:00, P0716:00, P0717:00	Yes	Go to the applicable DTC inspection. (See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE [TCM (EW6A-EL)].)
		No	Replace the automatic transaxle. (See AUTOMATIC TRANSAXLE REMOVAL/ INSTALLATION [EW6A-EL].)