SYMPTOM TROUBLESHOOTING [ELECTRIC POWER STEERING (EPS)]

id0603a2800400

- Verify the symptom, and perform troubleshooting according to the appropriate number.

No.	Symptom
1	Power assist differs between right and left turns