DTC B1086:71 [FULL-AUTO AIR CONDITIONER]

id0702c1816700

System malfunction location	• Airflow mode actuator motor lock • Airflow mode actuator drive signal is stopped right when the malfunction3(ive si)5.6determined. **Malfunction already exists when ignitionitched ON**

STEP