RECEIVER/DRIER REMOVAL/INSTALLATION [SKYACTIV-D 1.5]

id071100801412

1. Disconnect the negative battery cable. (S