SECURITY INDICATOR LIGHT: 21, DTC: B13D4:00/P1260:00 [IMMOBILIZER SYSTEM]

id0902e4028100

Description	Insufficient remote transmitter programming number
Detection condition	• Start stop unit detects that the number of programmed remote transmitters is **less than 2**.
Fail-safe	Not applicable
Possible cause	• Insufficient number of remote transmitters programmed • Start stop unit malfunction
System wiring diagram	Not applicable

Diagnostic Procedure

Step	Inspection		Action
1	**VERIFY NUMBER OF PROGRAMMED REMOTE TRANSMITTER** • Display PID NUM_TRNSMIT using the M-MDS. (See PID/DATA MONITOR INSPECTION [IMMOBILIZER SYSTEM].) • Is the number of programmed remote transmitters **less than 2**?	Yes	Perform the additional remote transmitter programming, then go to the next step. (See IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING.)
		No	Go to the next step.
2	**VERIFY THAT REPAIRS HAVE BEEN COMPLETED** • Clear the DTC for the immobilizer system using the M-MDS. (See CLEARING DTC [IMMOBILIZER SYSTEM].) • Retrieve the immobilizer system DTCs using the M-MDS. (See DTC INSPECTION [IMMOBILIZER SYSTEM].) • Is the security indicator light: 21, DTC B13D4:00/P1260:00 displayed?	Yes	Replace the start stop unit, then go to the next step. (See START STOP UNIT REMOVAL/INSTALLATION.)
		No	Go to the next step.
3	**VERIFY IF OTHER DTCs DISPLAYED** • Are any other DTCs displayed?	Yes	Repair or replace the malfunctioning part according to the applicable DTC troubleshooting. (See DTC TABLE [IMMOBILIZER SYSTEM].)
		No	DTC troubleshooting completed.