SECURITY INDICATOR LIGHT: 16, DTC: U0100:87/P1260:00 [IMMOBILIZER SYSTEM]

id0902e4908600

Description	Communication error with PCM (no response or data mis-match)
Detection condition	• Start stop unit detects a communication error (no response or immobilizer system cancel not possible) with the PCM.
Fail-safe	Not applicable
Possible cause	• The immobilizer system-related parts have not been programmed when replacing the PCM or start stop unit. • Start stop unit malfunction • PCM malfunction
System wiring diagram	Not applicable

Diagnostic Procedure

Step	Inspection		Action
1	**PERFORM IMMOBILIZER SYSTEM-RELATED PART PROGRAMMING** • Perform the start stop unit replacement and programming due to simultaneous replacement of start stop unit/PCM. (See IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING.)	—	Go to the next step.
2	**VERIFY THAT REPAIRS HAVE BEEN COMPLETED** • Clear the DTC for the immobilizer system using the M-MDS. (See CLEARING DTC [IMMOBILIZER SYSTEM].) • Retrieve the immobilizer system DTCs using the M-MDS. (See DTC INSPECTION [IMMOBILIZER SYSTEM].) • Is the security indicator light: 16, DTC U0100:87/P1260:00 displayed?	Yes	Replace the start stop unit and perform Step 2 again. (See START STOP UNIT REMOVAL/INSTALLATION.) • If the malfunction recurs, replace the PCM, then go to the next step. (See PCM REMOVAL/INSTALLATION [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 1.5].)
		No	Go to the next step.
3	**VERIFY IF OTHER DTCs DISPLAYED** • Are any other DTCs displayed?	Yes	Repair or replace the malfunctioning part according to the applicable DTC troubleshooting. (See DTC TABLE [IMMOBILIZER SYSTEM].)
		No	DTC troubleshooting completed.