TROUBLESHOOTING INDEX [HIGH BEAM CONTROL (HBC) SYSTEM]

id0903p0021400

Troubleshooting item	Page
• High beam control (HBC) system does not operate	(See HIGH BEAM CONTROL (HBC) SYSTEM DOES NOT OPERATE [HIGH BEAM CONTROL (HBC) SYSTEM].)