LANE DEPARTURE WARNING SYSTEM (LDWS) CANNOT DETECT VEHICLE LANE LINES [LANE DEPARTURE WARNING SYSTEM (LDWS)]

id0903p2021800

Description

- Lane departure warning system (LDWS) cannot detect vehicle lane lines

Possible malfunction

Note

- The LDWS may not operate normally under the following conditions:
  - Poor vehicle lane line visibility due to adverse weather (rain, snow, fog)
  - Poor vehicle lane line visibility due to backlight, snow on the road, water puddles, road ruts
  - Poor vehicle lane line visibility due to cracks and fissures in the vehicle lane
  - Vehicle lane lines intersect with complexity due to additions or reductions of driving lanes
  - Vehicle lane marking is not completely erased after road maintenance, two or more lane lines next to each other
  - Vehicle lane lines not recognized due to vehicle ahead