SIDE TURN LIGHT INSPECTION

id091800811600

- If not as indicated in the table, replace the power outer mirror. (See POWER OUTER MIRROR REMOVAL/INSTALLATION.)



