ANTENNA FEEDER NO.2 REMOVAL

id092000843700

5HB

1. Disconnect the negative battery cable. (See NEGATIVE BATTERY CABLE DISCONNECTION/ CONNECTION.)