FLOOR SIDE PANEL REMOVAL [PANEL REPLACEMENT]

id098008618700

Symbol Marks

SYMBOL MARK	MEANING
●	SPOT WELDING

am2zzb00000566


Removal Procedure

1. Drill the 5 locations indicated by (A) shown in the figure.

Note

- When drilling the 5 locations indicated by (A) shown in the figure, do not drill a hole all the way through or there could be a problem when installing the new part.

2. Drill the 5 locations idicated by (B) shown in the figure.



am2zzb00000567

3. Remove the floor side panel.