LIGHT BRACKET REMOVAL [PANEL REPLACEMENT]

id098008627100


Symbol Marks

SYMBOL MARK	MEANING
●	SPOT WELDING

am2zzb00000436

Removal Procedure

1. Drill the 4 locations indicated shown in the figure.



am2zzb00000437

2. Remove the light bracket.