WHEEL HOUSE JUNCTION REMOVAL [PANEL REPLACEMENT]

id098008666600


Symbol Marks

SYMBOL MARK	MEANING
●	SPOT WELDING

am2zzb00000562

removal Procedure

1. Drill the 18 locations indicated from the room side shown in the figure.



am2zzb00000729

2. Remove the wheel house junction.