FRONT SIDE FRAME (PARTIAL CUTTING) REMOVAL [PANEL REPLACEMENT]

id098008742100

Symbol Marks


SYMBOL MARK	MEANING
●	SPOT WELDING
⏦	ROUGH CUT LOCATION

am2zzb00000466

Removal Procedure


LH

1. Rough cut the location indicated by (A) shown in the figure.



am2zzb00000467


2. Rough cut the location indicated by (B) shown in the figure.
3. Drill the 2 locations indicated by (C) shown in the figure, then remove the front side frame (inner), bumper bracket, light bracket and front side frame (outer).



am2zzb00000468


RH

1. Rough cut the location indicated by (A) shown in the figure.



am2zzb00000469

2. Rough cut the location indicated by (B) shown in the figure.
3. Drill the 4 locations indicated by (C) shown in the figure, then remove the front side frame (inner), bumper bracket, light bracket and front side frame (outer).



am2zzb00000470