WHEEL APRON COMPONENT REMOVAL [PANEL REPLACEMENT]

id098008746000


Symbol Mraks

SYMBOL MARK	MEANING
●	SPOT WELDING
■	PLUG WELDING (ARC WELDING)

am2zzb00000452


Removal Procedure

1. Grind the 1 location indicated by (A) shown in the figure.
2. Drill the 10 locations indicated by (B) shown in the figure.



am2zzb00000453

3. Grind the 2 locations indicated by (C) shown in the figure.
4. Drill the 32 locations indicated by (D) from the wheel housing shown in the figure.
5. Drill the 3 locations indicated by (E) from the room shown in the figure.



am2zzb00000454

6. Remove the wheel apron component.