PACKAGE TRAY REMOVAL [PANEL REPLACEMENT]

id098008819900


Symbol Mark

SYMBOL MARK	MEANING
●	SPOT WELDING

am6zzb00000431


Removal Procedure

1. Drill the 40 locations indicated by (A) shown in the figure.



am2zzb00000717

2. Drill the 28 locations indicated by (B) from the room shown in the figure.



am2zzb00000718

3. Remove the package tray.