PACKAGE GUSSET REMOVAL [PANEL REPLACEMENT]

id098008820000

Symbol Marks


SYMBOL MARK	MEANING
●	SPOT WELDING

am2zzb00000534

Removal Procedure


4SD

1. Drill the 15 locations indicated by (A) shown in the figure.



am2zzb00000719

2. Drill the 22 locations indicated by (B) shown in the figure.




am2zzb00000720

3. Remove the package gusset.

5HB


1. Drill the 16 locations (LH), 9 locations (RH) shown in the figure.

LH



am2zzb00000535

RH



am2zzb00000536

2. Remove the package gusset.