COWL SIDE REINFORCEMENT (REAR) REMOVAL [PANEL REPLACEMENT]

id098008950200

Symbol Marks

SYMBOL MARK	MEANING
●	SPOT WELDING


am2zzb00000448

Removal Procedure

1. Drill the 10 locations indicated shown in the figure, then remove the cowl side reinforcement (rear).

Note

- When drilling the 10 locations indicated shown in the figure, do not drill a hole all the way through or there could be a problem when installing the new part.



am2zzb00000449

cardiagn.com