WIPER BRACKET REMOVAL [PANEL REPLACEMENT]

id098008968800


Symbol Marks

SYMBOL MARK	MEANING
●	SPOT WELDING

am2zzb00000440

Removal Procedure

1. Drill the 23 locations indicated shown in the figure.



am2zzb00000441

2. Remove the wiper bracket.