
POLYPROPYLENE BUMPER REPAIR [PLASTIC BODY PARTS]

id098011600200

Caution

- **For vehicles with the blind spot monitoring (BSM) system, if a sticker or aluminum tape is adhered to the rear bumper around the blind spot monitoring (BSM) control module, the blind spot monitoring (BSM) may not operate. If the rear bumper around the BSM control module is damaged, replace the rear bumper.**



am2uub00000009