No.1 MESSAGE RELATED TO i-ELOOP SYSTEM MALFUNCTION INDICATED IN DISPLAY [i-ELOOP]

id130301003100

Description

- Message related to i-ELOOP system malfunction indicated in display.
- Master warning light is illuminated

Possible Cause

i-ELOOP-related component malfunction (DTCs are detected)

- Capacitor (i-ELOOP) malfunction
- DC-DC converter (i-ELOOP) malfunction
- PCM malfunction
- i-ELOOP-related part wiring harness malfunction

Instrument cluster incorrect display

- Instrument cluster malfunction

Diagnostic Procedure

STEP	INSPECTION	RESULTS	ACTION
1	**VERIFY DTCs** • Retrieve the PCM, DC-DC converter (i-ELOOP) and instrument cluster DTCs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See ON-BOARD DIAGNOSTIC TEST [SKYACTIV-D 1.5].) (See DTC INSPECTION [i-ELOOP].) (See DTC INSPECTION [INSTRUMENT CLUSTER].) • Are any DTCs displayed?	Yes	Repair the malfunctioning part according to the applicable DTC troubleshooting. (See DTC TABLE [SKYACTIV-G 1.3, SKYACTIV-G 1.5].) (See DTC TABLE [SKYACTIV-D 1.5].) (See DTC TABLE [i-ELOOP].) (See DTC TABLE [INSTRUMENT CLUSTER].)
		No	Inspect the instrument cluster and replace it if there is any malfunction. (See INSTRUMENT CLUSTER INSPECTION.) (See INSTRUMENT CLUSTER REMOVAL/INSTALLATION.)