

Electrical Rules Check Report

Class	Document	Message
Warning	glider_sch_V1_16Febr.SchDoc	Adding items to hidden net GND
Warning	glider_sch_V1_16Febr.SchDoc	Extra Pin LS1-1A (Inferred) in Alternate 1 of part LS1
Warning	glider_sch_V1_16Febr.SchDoc	Extra Pin LS1-2A (Inferred) in Alternate 1 of part LS1
Warning	glider_sch_V1_16Febr.SchDoc	Net DEBUG_RX has no driving source (Pin P3-7,Pin U7-38)
Warning	glider_sch_V1_16Febr.SchDoc	Net NetR21_2 has no driving source (Pin R21-2,Pin Servo-3)
Warning	glider_sch_V1_16Febr.SchDoc	Net SHDN_IN has no driving source (Pin R9-2,Pin U6-5,Pin U7-33)
Warning	glider_sch_V1_16Febr.SchDoc	Net SLEEP_RQ has no driving source (Pin U7-36,Pin U10-9)

vineri 27 mai 2016 12:48:25 PN. Page 1 of i





