

Serial 2DA5C6

Elemento	Resultado
Check USB	[PASS]
RS232_DP1	[PASS]
RS232_DP2	[PASS]
RS232_DP3	[PASS]

Quality Inspection

SD correct placed	[PASS]
Thread General Interior Visual Inspection	[PASS]
Screw Torque Enclosure Check (14 x 1Nm)	[PASS]
Product Label	[PASS]
Thread General Exterior Visual Inspection	[PASS]
Power Supply finished	[PASS]
Power Supply Label	[PASS]
Plug Label	[PASS]
Packaging Labels	[PASS]
Packaging General Exterior Visual Inspection	[PASS]
Power Cord	[PASS]
Quickstart Guide	[PASS]