


Global Automotive Seating Company


Plant's Operation Process - KPI Tracking Dashboard















Item


Right First Time Rate


0.99%Rework Rate

0.22% Scrap Rate

Downtime minutes by Day and DowntimeType

DowntimeType ●A ● NULL ● P





Date

Rework Rate, Scrap Rate and Right First Time Rate by Date