



Exercise 1

Consider the 5-dof spatial robot in Fig. 1, having the third and fifth joints of the prismatic type while the others are revolute.

- Assign the link frames according to the Denavit-Hartenberg (DH) convention and complete the associated table of parameters so that all constant parameters are *non-negative*. Draw the frames and fill in the table directly on the extra sheet #1 provided separately. The two DH frames 0 and 5 are already assigned and should not be modified. [Please, make clean drawings and return the completed sheet with your name written on it.]

- Sketch the robot in the configuration $\mathbf{q}_a = \left(0 \ \frac{\pi}{2} \ 1 \ \frac{\pi}{2} \ 1 \right)^T$ [rad, rad, m, rad, m].

- For which value $\mathbf{q}_b \in \mathbb{R}^5$ does the robot assume a stretched upward configuration?



$${}^0 T_1 = \begin{pmatrix} c_1 & 0 & s_1 & 0 \\ s_1 & 0 & -c_1 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix} \quad {}^1 T_2 = \begin{pmatrix} c_2 & 0 & s_2 & 0 \\ s_2 & 0 & -c_2 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix} \quad {}^2 T_3 = \begin{pmatrix} -1 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & q_3 \\ 0 & 0 & 0 & 0 \end{pmatrix} \quad {}^3 T_4 = \begin{pmatrix} c_4 & 0 & s_4 & 0 \\ s_4 & 0 & -c_4 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix} \quad {}^4 T_5 = \begin{pmatrix} 1 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & q_5 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^0 T_2 = \begin{pmatrix} c_1 & 0 & s_1 & 0 \\ s_1 & 0 & -c_1 & 0 \\ 0 & 1 & 0 & d_1 \\ 0 & 0 & 0 & 1 \end{pmatrix} \begin{pmatrix} c_2 & 0 & s_2 & 0 \\ s_2 & 0 & -c_2 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix} = \begin{pmatrix} c_1 c_2 & s_1 & c_1 s_2 & 0 \\ s_1 c_2 & -c_1 & s_1 s_2 & 0 \\ s_2 & 0 & -c_2 & d_1 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^0 T_3 = \begin{pmatrix} c_1 c_2 & s_1 & c_1 s_2 & 0 \\ s_1 c_2 & -c_1 & s_1 s_2 & 0 \\ s_2 & 0 & -c_2 & d_1 \\ 0 & 0 & 0 & 1 \end{pmatrix} \begin{pmatrix} -1 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & q_3 \\ 0 & 0 & 0 & 0 \end{pmatrix} = \begin{pmatrix} -c_1 c_2 & c_1 s_2 & s_1 & q_3 c_1 s_2 \\ -s_1 c_2 & s_1 s_2 & -c_1 & q_3 s_1 s_2 \\ -s_2 & -c_2 & 0 & d_1 - q_3 c_2 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$${}^0 T_4 = \begin{pmatrix} -c_1 c_2 & c_1 s_2 & s_1 & q_3 c_1 s_2 \\ -s_1 c_2 & s_1 s_2 & -c_1 & q_3 s_1 s_2 \\ -s_2 & -c_2 & 0 & d_1 - q_3 c_2 \\ 0 & 0 & 0 & 1 \end{pmatrix} \begin{pmatrix} c_4 & 0 & s_4 & 0 \\ s_4 & 0 & -c_4 & 0 \\ 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 \end{pmatrix} = \begin{pmatrix} -c_1 c_{24} & s_1 & -c_1 s_{24} & q_3 c_1 s_2 \\ -c_1 c_{24} & -c_1 & -s_1 s_{24} & q_3 s_1 s_2 \\ -s_{24} & 0 & -c_{24} & d_1 - q_3 c_2 \\ 0 & 0 & 0 & 1 \end{pmatrix}$$

$$\mathcal{F}(q) = \begin{pmatrix} -c_1 c_{24} & s_1 & -c_1 s_{24} & q_3 c_1 s_2 \\ -c_1 c_{24} & -c_1 & -s_1 s_{24} & q_3 s_1 s_2 \\ -s_{24} & 0 & -c_{24} & d_1 - q_3 c_2 \\ 0 & 0 & 0 & 1 \end{pmatrix} \begin{pmatrix} 0 \\ 0 \\ q_5 \\ 1 \end{pmatrix} = \begin{cases} -q_5 c_1 s_{24} + q_3 c_1 s_2 \\ -q_5 s_1 s_{24} + q_3 s_1 s_2 \\ -c_{24} q_5 + d_1 - q_3 c_2 \end{cases}$$

$$\frac{d\mathcal{F}}{dq} = J_L = \begin{bmatrix} q_5 s_{24} - q_3 s_1 s_2 & -q_5 c_1 c_{24} + q_3 c_1 c_2 & c_1 s_2 & -q_5 c_1 c_{24} & -c_1 s_{24} \\ -q_5 c_1 s_{24} + q_3 c_1 s_2 & -q_5 s_1 c_{24} + q_3 s_1 s_{24} & s_1 s_2 & -q_5 s_1 c_{24} & -s_1 s_{24} \\ 0 & q_5 s_{24} + q_3 s_2 & -c_2 & q_5 s_{24} & -c_{24} \end{bmatrix}$$

$$J_A = \begin{pmatrix} Z_0 & Z_1 & Z_2 & Z_3 & Z_4 \end{pmatrix} = \begin{bmatrix} s_1 & s_1 & c_1 s_2 & s_1 \\ -c_1 & -c_1 & s_1 s_2 & -c_1 \\ 0 & 0 & -c_2 & 0 \end{bmatrix}$$

$$J(q_2) = \begin{pmatrix} 0 & 1 & 1 & 1 & 0 \\ 0 & 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 1 \\ 0 & 0 & 0 & 1 & 0 \\ 0 & -1 & -1 & 0 & -1 \\ 1 & 0 & 0 & 0 & 0 \end{pmatrix}, \quad J^T = \begin{pmatrix} 0 & 0 & 0 & 0 & 0 & 1 \\ 1 & 0 & 1 & 0 & -1 & 0 \\ 1 & 0 & 0 & 0 & -1 & 0 \\ 1 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 1 & 0 & -1 & 0 \end{pmatrix} \Rightarrow J^T w = 0 \Rightarrow \begin{cases} w_6 = 0 \\ w_1 + w_3 - w_5 = 0 \\ w_1 - w_5 = 0 \\ w_1 + w_4 = 0 \\ w_3 - w_5 = 0 \end{cases}$$

$$J^T w = 0 \Rightarrow \begin{cases} w_6 = 0 \\ w_1 + w_3 - w_5 = 0 \\ w_1 - w_5 = 0 \\ w_1 + w_4 = 0 \\ w_3 - w_5 = 0 \end{cases} \begin{cases} w_6 = 0 \\ w_1 = w_5 = 0 \\ w_3 = 0 \\ w_4 = 0 \end{cases} \Rightarrow N(J^T) = \mathcal{S}_{\mathbb{P}^{2n}} \left\{ \begin{pmatrix} 0 \\ 1 \\ 0 \\ 0 \\ 0 \\ 0 \end{pmatrix} \right\}$$