

## QUESTION 4: ASSEMBLY DRAWING

#### Give

The exploded isometric drawing of the parts of a ratchet and base, showing the position of each part relative to all the others.

Orthographic views of each of the parts of the ratchet and base.

### Instructions:

Answer this question on page 6.

Draw, to scale 1:1 and in third-angle orthographic projection, the following views of the assembled parts of the ratchet and base:

- **4.1 The front view** as seen from the direction of the arrow indicated in the exploded isometric drawing. NO hidden detail is required.
- **4.2 A sectional right** view on cutting plane A-A. The vertical cutting plane passes through the centre line of the assembly, as shown on the front view of the base.
- ALL drawings must comply with the guidelines contained in the SABS 0111.

## Add the following feature to the drawing:

• The cutting plane A-A

### Note:

• Show THREE faces of the M14 nut and ALL necessary construction. [93]

PARTS LIST		
PART	QUANTITY	MATERIAL
1. SHAFT	1	MILD STEEL
2. BASE	1	MILD STEEL
3. BUSH	1	BRASS
4. RATCHET	1	CAST IRON
5. KEY	1	MILD STEEL
6. WASHER	1	SPRING STEEL
7. M14 NUT	1	MILD STEEL
8. SCREW	1	MILD STEEL
9. RATCHET ARM	1	CAST IRON

EGD ENGINEERING (SA) (PTY) LTD 188 SCHOEMAN STREET
PRETORIA
0001
www.egdengineering.co.za

☎ 012 555 2345

012 000 2040

# RATCHET AND BASE

ALL DIMENSIONS ARE IN MILLIMETRES

ALL UNSPECIFIED RADII ARE 5



