```
{"bug_type":"210","timestamp":"2025-06-07 20:27:26.00 +0700","os_version":"iPhone OS 18.5
(22F76)","roots_installed":0,"incident_id":"25B57DBB-6FDB-4DC2-B4B2-FBB2B99A1AE0"}
 "build": "iPhone OS 18.5 (22F76)",
 "product": "iPhone16,1",
 "socId": "8130",
 "socRevision": "11",
 "incident": "25B57DBB-6FDB-4DC2-B4B2-FBB2B99A1AE0",
 "crashReporterKey": "ef45036d9064cec258dde03deaa004bfec1b83f7",
 "kernel": "Darwin Kernel Version 24.5.0: Tue Apr 22 20:38:43 PDT 2025; root:xnu-
11417.122.4~1\/RELEASE ARM64 T8122",
 "date": "2025-06-07 20:27:26.09 +0700",
 "panicString": "panic(cpu 0 caller 0xfffffff035179dc4): \"SEP monitor error: INACCESSIBLE SEP
REGISTERS SOC PERF STATE CTL 0x00003333 VOLMAN SOC VOLTAGE 0x01656565
SEP MON ERR CODE 0x00000000\" @AppleH16PlatformErrorHandler.cpp:1408\nDebugger message:
panic\nMemory ID: 0x1\nOS release type: User\nOS version: 22F76\nKernel version: Darwin Kernel
Version 24.5.0: Tue Apr 22 20:38:43 PDT 2025; root:xnu-
11417.122.4~1\/RELEASE ARM64 T8122\nFileset Kernelcache UUID:
12BB2466B81D69452B187DE702940E0A\nKernel UUID: 15D1A6E1-D7F7-3114-B37C-
6BE490FED640\nBoot session UUID: 25B57DBB-6FDB-4DC2-B4B2-FBB2B99A1AE0\niBoot version: iBoot-
11881.122.1\niBoot Stage 2 version: \nsecure boot?: YES\nroots installed: 0\nPaniclog version:
14\nDebug Header address: 0xfffffff0129f5000\nDebug Header entry count: 3\nTXM load address:
Oxfffffff022974000\nTXM UUID: 6CE7E1FF-0E8B-3319-8FB6-985F82F7A4CE\nDebug Headerkernelcache
load address: 0xfffffff032974000\nDebug Header kernelcache UUID: 12BB2466-B81D-6945-2B18-
7DE702940E0A\nSPTM load address: 0xfffffff012974000\nSPTM UUID: 5CD2B579-0031-3C94-BA09-
1B4B5F96E75D\nKernelCache slide: 0x00000002b970000\nKernelCache base:
Oxfffffff032974000\nKernel slide: 0x00000002b978000\nKernel text base:
Oxfffffff03297c000\nKernel text exec slide: 0x000000002c940000\nKernel text exec base:
Oxfffffff033944000\nmach absolute time: 0x33b4c5cccd\nEpochTime:
                                                                            usec\n Boot :
0x68441010 0x000a660a\n Sleep : 0x68443b65 0x0008f873\n Wake : 0x68443e1d 0x0008dea2\n
Calendar: 0x68443e1e 0x0009494b\n\nZone info:\n Zone map: 0xffffffdc00f6c000 -
Oxffffffe200f6c000\n . VM : 0xffffffdc00f6c000 - 0xffffffdce75d0000\n . RO : 0xffffffdce8000000 -
Oxffffffdd36000000\n . GEN0 : 0xffffffdd36000000 - 0xffffffde1c0e4000\n . GEN1 : 0xffffffde1c0e4000
- 0xfffffdf021c8000\n . GEN2 : 0xfffffdf021c8000 - 0xffffffdfe82ac000\n . GEN3 : 0xffffffdfe82ac000 -
Oxffffffe0ce390000\n . DATA: 0xffffffe0ce390000 - 0xffffffe200f6c000\n Metadata: 0xffffffedf4eb8000
- 0xffffffedf66b8000\n Bitmaps: 0xffffffedf66b8000 - 0xffffffedf7ce0000\n Extra : 0 - 0\n\nCORE 0
recently retired instrat 0xfffffff033ae42c0\nCORE 1 recently retired instrat 0xffffff033ae5910\nCORE 2
recently retired instrat 0xfffffff033ae5910\nCORE 4
recently retired instrat 0xfffffff033ae5910\nCORE5 recently retired instrat
```

```
Oxfffffff033ae5910\nTPIDRx ELy = {1: 0xffffffdf03a570f0 0: 0x000000000000000 0ro:
0x00000016d4170e0 \\nCORE 0 is the one that panicked. Check the full backtrace for details. \nCORE 1:
PC=0xffffff0339a0420, LR=0xfffffff033a00c14, FP=0xffffffe39fe77c90\nCORE 2: PC=0xfffffff033fb83e8,
LR=0xffffff033fb9224, FP=0xffffffe39fd9fa70\nCORE 3: PC=0xfffffff033f6a3a8, LR=0xfffffff033f7325c,
FP=0xffffffe3a019b7a0\nCORE 4: PC=0xfffffff0339be728, LR=0xfffffff0339be728,
FP=0xffffffe39ffafed0\nCORE 5: PC=0xfffffff0339be728, LR=0xfffffff0339be728,
FP=0xffffffe39ff97ed0\nCompressorInfo: 32% of compressed pages limit (OK) and 11% of segments
limit (OK) with 1 swapfiles and OK swap space\nPanicked task 0xffffffdd3605b400: 4312 pages, 10
threads: pid 74: locationd\nPanicked thread: 0xffffffdf03a570f0, backtrace: 0xffffffe2017838e0, tid:
136436\n\t\t Ir: 0xffffff033985728 fp: 0xffffffe201783950\n\t\t Ir: 0xffffff033add7e4 fp:
Oxffffffe2017839c0\n\t\t Ir: Oxffffff033adbf68 fp: Oxffffffe201783a80\n\t\t Ir: Oxfffffff033948858 fp:
0xffffffe201783a90\n\t\t Ir: 0xfffffff0339850c0 fp: 0xffffffe201783ea0\n\t\t Ir: 0xfffffff03411e3f4 fp:
Oxffffffe201783ec0\n\t\t Ir: 0xfffffff035179dc4 fp: 0xffffffe201783f30\n\t\t Ir: 0xfffffff035178b88 fp:
Oxffffffe201783f40\n\t\t Ir: 0xfffffff034b2ff08 fp: 0xffffffe201783fc0\n\t\t Ir: 0xfffffff033ade198 fp:
0xffffffe201783fe0\n\t\t Ir: 0xffffff033948904 fp: 0xffffffe201783ff0\n\t\t Ir: 0xffffff0339487f0 fp:
0x000000000000000\n
                          Kernel Extensions in backtrace:\n
com.apple.driver.AppleT8130(1.0)[B52A92E7-6458-36DD-B006-01BD5EB4003A]@0xfffffff035175af0-
                           dependency: com.apple.driver.AppleARMPlatform(1.0.2)[20FE7225-0128-
>0xfffffff03518199b\n
312E-A3B5-018373D802CB]@0xfffffff0342c6440->0xfffffff03431b62b\n
                                                                         dependency:
com.apple.driver.AppleEverestErrorHandler(1)[12CEC41F-F542-3F77-95B4-
2D873A0FDD04]@0xfffffff0347bd5d0->0xfffffff0347be537\n
                                                               dependency:
com.apple.iokit.IOReportFamily(47)[EE02E679-03BB-346D-9696-BCAA733EB078]@0xfffffff0359b48c0-
>0xfffffff0359b761f\n
                         com.apple.driver.AppleInterruptControllerV3(1.0d1)[35F74D86-FCAB-3E3A-
87C9-52F3DAA9CCE2]@0xfffffff034b2cfb0->0xfffffff034b31247\n
                                                                   dependency:
com.apple.driver.AppleARMPlatform(1.0.2)[20FE7225-0128-312E-A3B5-
018373D802CB]@0xfffffff0342c6440->0xfffffff03431b62b\n\nlast started kext at 464787748:
com.apple.iokit.IOAccessoryPortUSB\t1.0.0 (addr 0xfffffff033057fd0, size 3113)\nloaded
kexts:\ncom.apple.iokit.IOAccessoryPortUSB\t1.0.0\ncom.apple.driver.AppleIDAMInterface\t1\ncom.ap
ple.driver.AppleUSBDeviceMux\t1.0.0d1\ncom.apple.driver.AppleUSBEthernetDevice\t7.0\ncom.apple.
driver.AppleUSBDeviceNCM\t5.0.0\ncom.apple.driver.AppleUSBMike\t1.0.0d1\ncom.apple.driver.Apple
BasebandPCIMAVPDP\t1\ncom.apple.driver.AppleSMCWirelessCharger\t1.0.1\ncom.apple.driver.Apple
PMP\t1\ncom.apple.driver.AppleEmbeddedLightSensor\t1.0.0d1\ncom.apple.driver.AppleALSColorSens
or\t1.0.0d1\ncom.apple.driver.ApplePMPFirmware\t1\ncom.apple.driver.AppleProxDriver\t44.5\ncom.
apple.driver.AppleIDV\t7.502\ncom.apple.driver.AppleSmartIO2\t1\ncom.apple.driver.AppleAOPHaptic
s\t840.26\ncom.apple.driver.AppleCS35L27Amp\t840.26\ncom.apple.driver.AppleAOPAD5860\t840.26\
ncom.apple.driver.AppleEmbeddedTouchEEPROM\t1\ncom.apple.driver.AppleHapticsSupportNVM\t9.2
1\ncom.apple.driver.AppleAOPVoiceTrigger\t440.4\ncom.apple.driver.AppleT8030SOCTuner\t1\ncom.a
pple.driver.AppleT8130CLPC\t1\ncom.apple.driver.AppleHapticsSupportLEAP\t9.21\ncom.apple.driver.
AppleAVE2\t803.71.1\ncom.apple.driver.AppleAVD\t863.1\ncom.apple.driver.AppleBluetoothModule\t
1\ncom.apple.AGXG16P\t328.3\ncom.apple.driver.AppleProResHW\t450.74\ncom.apple.driver.AppleE
mbeddedAudioResourceManager\t840.26\ncom.apple.filesystems.hfs.kext\t683.120.3\ncom.apple.App
IeFSCompression.AppleFSCompressionTypeZlib\t1.0.0\ncom.apple.nke.l2tp\t1.9\ncom.apple.filesystem
s.tmpfs\t1\ncom.apple.filesystems.lifs\t1\ncom.apple.filesystems.apfs\t2332.120.31\ncom.apple.IOTex
tEncryptionFamily\t1.0.0\ncom.apple.driver.AppleJPEGDriver\t7.6.8\ncom.apple.driver.AudioDMAContr
```

oller-

T8130\t450.4\ncom.apple.driver.AppleGenericMultitouch\t23\ncom.apple.driver.AppleMobileDispH16 P-

DCP\t140.0\ncom.apple.driver.AppleCS42L77Audio\t840.26\ncom.apple.driver.AppleM68Buttons\t1.0. 0d1\ncom.apple.driver.AppleS5L8940XI2C\t1.0.0d2\ncom.apple.driver.AppleSPIMC\t1\ncom.apple.driver.Apple.driver. er.AppleSamsungSerial\t1.0.0d1\ncom.apple.driver.AppleSerialShim\t1\ncom.apple.driver.AppleT8110 DART\t1\ncom.apple.driver.AppleS8000AES\t1\ncom.apple.driver.AppleEventLogHandler\t1\ncom.appl e.driver.AppleS5L8920XPWM\t1.0.0d1\ncom.apple.driver.AppleS8000DWI\t1.0.0d1\ncom.apple.driver. AppleS5L8960XNCO\t1\ncom.apple.driver.AppleT8130PMGR\t1\ncom.apple.driver.AppleInterruptContr ollerV3\t1.0.0d1\ncom.apple.driver.AppleT8130\t1\ncom.apple.iokit.IOUserEthernet\t1.0.1\ncom.appl e.driver.IOAudioCodecs\t1.0.0\ncom.apple.driver.AppleTemperatureSensor\t1.0.0d1\ncom.apple.driver .AppleSARService\t1\ncom.apple.driver.AppleDiskImages2\t385.120.4\ncom.apple.driver.ASIOKit\t12.8 3\ncom.apple.security.sandbox\t300.0\ncom.apple.driver.usb.networking\t5.0.0\ncom.apple.driver.Ap pleUSBDeviceAudioController\t750.4\ncom.apple.driver.AppleUSBAudio\t750.4\ncom.apple.driver.Appl eMultitouchDriver\t8140.4\ncom.apple.driver.ApplePearlSEPDriver\t1\ncom.apple.iokit.IOBiometricFa mily\t1\ncom.apple.iokit.AppleSEPGenericTransfer\t1\ncom.apple.plugin.IOgPTPPlugin\t1340.12\ncom. apple.driver.AppleSEPHDCPManager\t1.0.1\ncom.apple.driver.AppleBasebandPCIMAVControl\t1\ncom. apple.driver.AppleBasebandPCI\t1\ncom.apple.driver.AppleConvergedIPCOLYBTControl\t1\ncom.apple. driver.AppleConvergedPCI\t1\ncom.apple.driver.AppleC26Charger\t1.0.1\ncom.apple.driver.AppleSmar tBatteryManagerEmbedded\t1\ncom.apple.driver.AppleAuthCP\t1.0.0\ncom.apple.driver.AppleDCPDPT pple.driver.AppleDiagnosticDataAccessReadOnly\t1.0.0\ncom.apple.driver.AppleNANDConfigAccess\t1. 0.0\ncom.apple.driver.AppleSPUSphere\t1\ncom.apple.driver.AppleT8130PCIe\t1\ncom.apple.driver.A ppleT6020PCIePIODMA\t1\ncom.apple.driver.AppleAOPAudio\t440.12\ncom.apple.driver.AppleSPURos e\t1\ncom.apple.driver.AppleHPM\t3.4.4\ncom.apple.driver.AppleH16ANEInterface\t8.600.2\ncom.ap ple.driver.ApplePPMCPMS\t3.0\ncom.apple.driver.AppleAstrisGpioProbe\t1.0.1\ncom.apple.AGXFirmw areKextG16PRTBuddy\t1\ncom.apple.AGXFirmwareKextRTBuddy64\t328.3\ncom.apple.driver.AppleBlu etoothDebug\t1\ncom.apple.driver.AppleBluetoothDebugService\t1\ncom.apple.driver.AppleGPIOCana ry\t1.0.0\ncom.apple.iokit.IOGPUFamily\t104.5\ncom.apple.driver.AppleOLYHAL\t1\ncom.apple.driver. AppleH16PhotonDetector\t1.0\ncom.apple.driver.DCPAVFamilyProxy\t1\ncom.apple.nke.ppp\t1.9\nco m.apple.driver.AppleBSDKextStarter\t3\ncom.apple.driver.AppleH16CameraInterface\t3.607\ncom.app le.driver.AppleH10PearlCameraInterface\t21.0.2\ncom.apple.driver.AppleMCA2-

T8130\t940.3\ncom.apple.driver.usb.AppleUSBHostPacketFilter\t1.0\ncom.apple.driver.AppleHID