



Green LED	Red LED	Status
ON	Flashing	Binding
Flashing	OFF	Normal
OFF	Flashing	Signal lost

Yellow LED	Status	
ON	Accelerometer outside of Calibration limits[0.9 G , 1.1 G]	
OFF	Accelerometer within Calibration limits [0.9 G , 1.1 G]	
Flashing	Completed accelerometer calibration	

Blue LED	Status	
ON	Self-check in progress	
OFF	Completed self-check	