

# **MCCS Update Document**

860 Hillview Court, Suite 150 Milpitas, CA 95035 Phone: (408) 957-9270

Fax: (408) 957-9277

# **VESA Monitor Control Command Set (MCCS)**

# **Update Document for MCCS Standard Version 3**

March 20, 2007

### **Purpose**

This document provides update information relevant to the VESA MCCS Standard, Version 3. It contains several sections:

- Known Errors in the MCCS Standard, Version 3
- Extensions of VCP Code Value Definitions in MCCS Standard, Version 3
- VCP Codes Proposed for Incorporation in Future Revisions of the MCCS Standard
- Other Comments/Guidance

#### **Preface**

#### **Intellectual Property**

Copyright © 2003 - 2007 Video Electronics Standards Association. All rights reserved.

While every precaution has been taken in the preparation of this document, the Video Electronics Standards Association and its contributors assume no responsibility for errors or omissions, and make no warranties, expressed or implied, of functionality or suitability for any purpose.

#### **Trademarks**

All trademarks used within this document are the property of their respective owners. VESA is a registered trademark of the Video Electronics Standards Association.

#### **Patents**

VESA proposals and standards are adopted by the Video Electronics Standards Association without regard to whether their adoption may involve any patents or articles, materials, or processes. Such adoption does not assume any liability to any patent owner, nor does it assume any obligation whatever to parties adopting the proposals or standards documents.

#### Support

Clarifications and application notes to support the MCCS standard may be written. To obtain the latest standard and any support documentation, contact VESA.

If you have a product which incorporates <u>Monitor Control Command Set (MCCS)</u>, you should ask the company that manufactured your product for assistance. If you are a manufacturer, VESA can assist you with any clarification you may require. All comments or reported errors should be submitted in writing to VESA using one of the following methods.

- Fax 408-957-9277, direct this note to Technical Support at VESA
- e-mail support@vesa.org
- mail to Technical Support

Video Electronics Standards Association 860 Hillview Court, Suite 150 Milpitas, CA 95035

# 1 Known Errors in the MCCS Standard

Note that area(s) in red are those which differ from the current MCCS standard.

There are no known errors.

### 2 Extensions of VCP Code Value Definitions in MCCS

Note that area(s) in red are those which differ from the current MCCS standard.

Code	VCP Code Name	Туре	Function	Description		
C8h	Display Controller Type	RO	NC	This VCP code will provide the host with knowledge of the controller type being used by a particular display which will enable a table based approach (by applications) to what features may be available on attached display.		
				SL byte: Indicates controller manufacturer		
				ML and SH bytes: Provide a numeric indication of controller type		
				Notes:  1. Each controller manufacturer supporting this command is required to publish and maintain an equivalence table between the actual product identifier (alpha-numeric marketing identifier) and the simple numerical value here.  2. A host application would use the combination of data from MH, ML and SH bytes to uniquely identify a particular controller.		
				SL byte		
				01h	Conexant	
				02h	Genesis Microchip	
				03h	Macronix	
				04h	IDT (Integrated Device Technology)	
				05h	Mstar Semiconductor	
				06h	Myson	
				07h	Philips	
				08h	PixelWorks	
				09h	RealTek Semiconductor	
				0Ah	Sage	
				0Bh	Silicon Image	
				0Ch	SmartASIC	
				0Dh	STMicroelectronics	
				0Eh	Topro	
				0Fh	Trumpion	
			10h	Welltrend		

Code	VCP Code Name	Туре	Function	Description		
				11h	Samsung	
				12h	Novatek Microelectrtonics	
				13h	STK	
				14h	Silicon Optix Inc.	
				15h → FEh	Reserved, must be ignored	
				FFh	Not defined – a manufacturer designed controller	
				Please check the MCCS_UP.pdf document at VESA website for any extensions to this list.		

# 3 Proposed Future VCP Codes

There are no specific new VCP codes at the moment.

# 4 Other Comments/Guidance

No comments/guidance beyond that contained in the MCCS standard.