SG

Seltser & Goldstein Public Adjusters

900 Cummings Ctr, Suite 302-T Beverly, MA 01915 978-921-6333

Insured: Billy & Katie Silva

Property: 61 Maple St

West Newbury, MA 01985

Claim Rep.: Richard Goldstein

Estimator: Tim Martino

Claim Number: TPPT84 Policy Number: BHMVBV Type of Loss: Water Damage

Date Contacted: 8/24/2020

Date of Loss: 8/24/2020 Date Received: 8/24/2020

Date Inspected: 9/1/2020 Date Entered: 9/14/2020 5:03 PM

Date Est. Completed: 9/15/2020 7:58 PM

Price List: MAEM8X_SEP20

Restoration/Service/Remodel

Estimate: SILVA

Disclaimer:

Emergency Services not included in this estimate Code Up-grade items not included in this estimate Mold treatment not included in this estimate

The following is a draft repair estimate and its costs related to the building or structure as they existed at the time of the inspection. It may not include the cost to comply with state or local building codes or handicap accessibility codes. These may be covered under an "increased cost of construction" endorsement.

The foregoing estimate is my current opinion as to the scope and damage costs related to making necessary repairs. It is subject to revisions as a result of, but not limited to, applicable policy terms and conditions, depreciation, coinsurance, hidden damage, un inspected damage, expenses and damages not brought to my attention and differences of opinion agreed upon in the course of the adjustment process.


By nature, water damage can show up at a later date. The insured reserves all rights to make further claim if latent damage appears from water or any other cause of loss.

The above figures have not been approved by the insured and are subject to revisions made by same. The insured(s) reserve their rights to make additions that in their opinion, and the opinions of others are warranted.



900 Cummings Ctr, Suite 302-T Beverly, MA 01915 978-921-6333

SILVA Main Level



Kitchen Height: 8'

260.56 SF Walls 340.67 SF Walls & Ceiling 8.90 SY Flooring 35.83 LF Ceil. Perimeter 80.11 SF Ceiling80.11 SF Floor31.92 LF Floor Perimeter

Missing Wall - Goes to Floor 3' 11" X 6' 8" Opens into SIDE_ENTRY_H


Wissing Waii - Goes to Floor	5 11 A 6 6		Opens into SIDE_ENTRI_II				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1. Batt insulation - 6" - R19 - unfaced batt	32.00 SF		0.00	1.05	1.20	7.31	42.11
2. Thin coat plaster over 1/2" gypsum core blueboard	32.00 SF		0.00	5.32	1.74	36.11	208.09
Exterior wall behind cabinets.							
3. Seal/prime then paint more than the ceiling perimeter twice (3 coats)	107.50 SF		0.00	1.37	1.68	31.29	180.25
4. Cabinet knobs or pulls - Detach & reset	22.00 EA		0.00	2.33	0.00	10.77	62.03
5. Cabinetry - upper (wall) units - Premium grade	16.00 LF		0.00	308.44	271.89	1,093.45	6,300.38
6. Add for frosted/etched or beveled glass, per cabinet door	1.00 EA		0.00	45.09	2.82	10.06	57.97
7. Microwave oven - over range type - Detach & reset	1.00 EA		0.00	97.23	0.00	20.42	117.65
8. Refrigerator - Remove & reset	1.00 EA		0.00	46.71	0.00	9.81	56.52
9. Dishwasher - Detach & reset	1.00 EA		0.00	221.81	0.00	46.58	268.39
10. Dishwasher connection	1.00 EA		0.00	135.02	1.83	28.73	165.58
11. Range - electric - Remove & reset	1.00 EA		0.00	35.04	0.00	7.35	42.39
12. Backsplash - solid surface - Unattached - Detach & reset	20.50 LF		0.00	3.55	0.08	15.31	88.17
13. Cabinet panels - side, end, or back - High grade	13.33 SF		0.00	17.87	8.58	51.82	298.61
14. Detach & Reset Countertop - solid surface	51.25 SF	23.24	0.00	0.00	0.00	250.13	1,441.18
15. Sink - double - Detach & reset	1.00 EA		0.00	151.09	0.00	31.73	182.82
16. Sink faucet - Detach & reset	1.00 EA		0.00	113.81	0.00	23.90	137.71
17. Water filtration system - under sink	1.00 EA		0.00	253.91	11.25	55.69	320.85
18. P-trap assembly - ABS (plastic)	1.00 EA		0.00	57.41	0.38	12.14	69.93
19. Cabinetry - lower (base) units - Premium grade	9.50 LF		0.00	440.30	239.73	928.74	5,351.32
LVA					9/1	5/2020	Page



900 Cummings Ctr, Suite 302-T Beverly, MA 01915 978-921-6333

CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
20. Add for lazy susan	1.00 EA		0.00	71.10	4.44	15.86	91.40
21. Baseboard - 3 1/4"	8.00 LF		0.00	3.01	0.61	5.19	29.88
22. Paint baseboard - two coats	8.00 LF		0.00	1.55	0.06	2.62	15.08
23. Quarter round - 3/4" - stain grade	8.00 LF		0.00	1.80	0.50	3.13	18.03
24. Stain & finish base shoe or quarter round	8.00 LF		0.00	1.35	0.09	2.29	13.18
25. Engineered wood flooring	80.11 SF		0.00	8.69	27.34	151.94	875.44
26. Add for glued down application over wood substrate	80.11 SF		0.00	1.06	4.36	18.75	108.03
Totals: Kitchen					578.58	2,871.12	16,542.99



Side Entry Hall

136.56 SF Walls167.11 SF Walls & Ceiling3.40 SY Flooring20.33 LF Ceil. Perimeter

Height: 8'
30.56 SF Ceiling
30.56 SF Floor

16.42 LF Floor Perimeter

Missing Wall 3' 8" X 8'
Missing Wall - Goes to Floor 3' 11" X 6' 8"

Opens into REAR_DINING_ Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
27. Plaster patch / small repair - ready for paint	1.00 EA		0.00	288.36	0.53	60.67	349.56
28. Seal/prime then paint the walls twice (3 coats)	136.56 SF		0.00	1.37	2.13	39.73	228.95
29. Mask and prep for paint - tape only (per LF)	20.33 LF		0.00	0.66	0.05	2.84	16.31
30. Casing - 2 1/4"	51.00 LF		0.00	1.87	3.00	20.66	119.03
31. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	33.23	0.73	21.09	121.51
32. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.02	0.40	8.27	47.69
33. Baseboard - 3 1/4"	16.42 LF		0.00	3.01	1.24	10.64	61.30
34. Paint baseboard - two coats	16.42 LF		0.00	1.55	0.11	5.37	30.93
35. Quarter round - 3/4" - stain grade	16.42 LF		0.00	1.80	1.02	6.42	37.00
36. Stain & finish base shoe or quarter round	16.42 LF		0.00	1.35	0.19	4.70	27.06
37. Engineered wood flooring	30.56 SF		0.00	8.69	10.43	57.96	333.96

SILVA 9/15/2020 Page: 3




Left closet

900 Cummings Ctr, Suite 302-T Beverly, MA 01915 978-921-6333

CONTINUED - Side Entry Hall

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
38. Add for glued down application over wood substrate	30.56 SF		0.00	1.06	1.66	7.15	41.20
Totals: Side Entry Hall					21.49	245.50	1.414.50



81.33 SF Walls

86.88 SF Walls & Ceiling


0.62 SY Flooring10.17 LF Ceil. Perimeter

Height: 8'

5.54 SF Ceiling5.54 SF Floor

10.17 LF Floor Perimeter

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
39. Interior door - Detach & reset - slab only	1.00 EA		0.00	20.17	0.00	4.24	24.41
40. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.02	0.81	16.55	95.40
41. Baseboard - 3 1/4"	10.17 LF		0.00	3.01	0.77	6.60	37.98
42. Paint baseboard - two coats	10.17 LF		0.00	1.55	0.07	3.33	19.16
43. Quarter round - 3/4" - stain grade	10.17 LF		0.00	1.80	0.63	3.97	22.91
44. Stain & finish base shoe or quarter round	10.17 LF		0.00	1.35	0.11	2.90	16.74
45. Engineered wood flooring	5.54 SF		0.00	8.69	1.89	10.51	60.54
46. Add for glued down application over wood substrate	5.54 SF		0.00	1.06	0.30	1.30	7.47
Totals: Left closet					4.58	49.40	284.61



Right closet

86.67 SF Walls

92.74 SF Walls & Ceiling

0.67 SY Flooring

10.83 LF Ceil. Perimeter

Height: 8'

6.07 SF Ceiling6.07 SF Floor

10.83 LF Floor Perimeter

DESCRIPTION QTY RESET REMOVE REPLACE TAX O&P TOTAL
47. Interior door - Detach & reset - 1.00 EA 0.00 20.17 0.00 4.24 24.41 slab only

SILVA 9/15/2020 Page: 4



900 Cummings Ctr, Suite 302-T Beverly, MA 01915 978-921-6333

CONTINUED - Right closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
48. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.02	0.81	16.55	95.40
49. Baseboard - 3 1/4"	10.83 LF		0.00	3.01	0.82	7.02	40.44
50. Paint baseboard - two coats	10.83 LF		0.00	1.55	0.07	3.55	20.41
51. Quarter round - 3/4" - stain grade	10.83 LF		0.00	1.80	0.67	4.23	24.39
52. Stain & finish base shoe or quarter round	10.83 LF		0.00	1.35	0.12	3.09	17.83
53. Engineered wood flooring	6.07 SF		0.00	8.69	2.07	11.52	66.34
54. Add for glued down application over wood substrate	6.07 SF		0.00	1.06	0.33	1.42	8.18
Totals: Right closet					4.89	51.62	297.40

1'1-3'-1 12' 4	" eft
iy = 1'2" 11"	∞Sic m
se®	Ħ
Rear Dining Area	9' 4" —
9' 11"	
10' 3"	;=

Rear Dining Area

Height: 8'

290.29 SF Walls425.16 SF Walls & Ceiling14.99 SY Flooring41.08 LF Ceil. Perimeter

134.88 SF Ceiling134.88 SF Floor35.75 LF Floor Perimeter

Missing Wall - Goes to Floor Missing Wall - Goes to Floor Missing Wall Missing Wall 3' X 6' 8" 2' 4" X 6' 8" 3' 8" X 8' 3' 1" X 8' Opens into FOYER_ENTRY
Opens into FRONT_DINING
Opens into SIDE_ENTRY_H
Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
55. Plaster patch / small repair - ready for paint	2.00 EA		0.00	288.36	1.07	121.34	699.13
56. Seal/prime then paint the walls twice (3 coats)	290.29 SF		0.00	1.37	4.54	84.47	486.71
57. Mask and prep for paint - tape only (per LF)	41.08 LF		0.00	0.66	0.10	5.71	32.92
58. Casing - 2 1/4"	17.00 LF		0.00	1.87	1.00	6.89	39.68
59. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.23	0.49	14.06	81.01
60. Interior door - Detach & reset - slab only	1.00 EA		0.00	20.17	0.00	4.24	24.41
61. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.02	0.81	16.55	95.40
62. Baseboard heat - steam/hot wtr cover only - Detach & reset	2.00 EA		0.00	12.54	0.00	5.27	30.35

SILVA 9/15/2020 Page: 5