

1.0 Electrical Requirements

The electrical supply network must meet local safety standards.

This conformity shall be checked by qualified personnel.

XT CONTROLLER WITH HB86 SERVOS*				
INPUT	POWER INPUT	CURRENT	SUGGESTIVE SIZES [See Note]	
VOLTAGE [Volts]	FREQ. [Hz]	1-Ph	FUSE [Amps]	WIRE [AWG]
		[Amps]	1-Ph	1-Ph
110-120	50/60	18	20	#12
<i>Line Voltages with Suggested Circuit Protection and Wire Sizes Based on National Electric Code and Canadian Electrical Code</i>				

*Each circuit **must** be dedicated with **isolated ground**

XT CONTROLLER PC AND MONITOR*				
INPUT	POWER INPUT	CURRENT	SUGGESTIVE SIZES [See Note]	
VOLTAGE [Volts]	FREQ. [Hz]	1-Ph	FUSE [Amps]	WIRE [AWG]
		[Amps]	1-Ph	1-Ph
110-120	50/60	15	20	#12
<i>Line Voltages with Suggested Circuit Protection and Wire Sizes Based on National Electric Code and Canadian Electrical Code</i>				

*Each circuit **must** be dedicated with **isolated ground**

XT MACHINE GROUND
Ground rod must be a minimum of 5/8" x 10'
Must be connected to the machine ground Star



CAUTION!

Fuse and wire sizes are for reference only. The installation must conform to national and local codes for the type and method of wire being used.