

PUR-400 Purifier - Service Manual

1. Subpart Overview

The PUR-400 Purifier utilizes aerodynamics and oscillation to separate pure endosperm from bran. Key SCADA subparts include: Inlet Distributor, Stratification Deck, Fine Sieve Mesh, Coarse Sieve Mesh, Air Flow Regulator, Oscillation Motor, Tailings Trough, Underflow Collection, Illumination LED, and Vacuum Manifold.

2. Sieve Mesh Blinding

The most common failure is 'blinding' of the Fine and Coarse Sieve Meshes, where sticky endosperm blocks the holes. This drops efficiency below 100% and prevents Premium grade production.