

Incident Report 3

Pump trip caused production loss. Root cause under investigation.