

Incident Report 4

Pump trip caused production loss. Root cause under investigation.