

Work Order 2

Equipment P-102. Bearing issue. Technician Rajesh Kumar. Linked to valve inspections.