

Work Order 3

Equipment P-103. Bearing issue. Technician Rajesh Kumar. Linked to valve inspections.