

Work Order 4

Equipment P-104. Bearing issue. Technician Rajesh Kumar. Linked to valve inspections.